| State of California — The Resources Agency | Primar | у | | | | |
|--|---|--|--|--|--|--|
| DEPARTMENT OF PARKS AND RECREATION | HRI# | | | | | |
| PRIMARY RECORD | | Trinomial | | | | |
| Other | NRHP : | Status Code | | | | |
| Review Code | Reviewer | | | Dat | e | |
| | #: (Assigned by Recorde | ar) 5601 S. Boyle Av | Α. | | | |
| rage O 4 Resource Name or | #. (Assigned by Records | er) 500 r S. Boyle Av | е. | | | |
| P1. Other Identifier: | | | | | | |
| *P2. Location: Not for Publication X Unrestricted | d *a. Co | ounty Los Angeles | | | | |
| and (P2b and P2c or P2d. Attach a Location Map as neces | • / | | | | D.M | |
| · | e 1978 T 2S | ; R 13W ; | _¹¼ of | ¼ of Sec | ; S.B. B.M | |
| c. Address 5601 S. Boyle Ave. d. UTM: (Give more than one for large and/or linear resour | rces) Zone: 11 | City Vernon | mE/ | | Zip <u>90058</u> mN | |
| , · | , <u>—</u> | | | - | | |
| e. Other Locational Data: (e.g. parcel #, directions to reso APN # 6310-011-003 | urce, elevation, etc., as a | ippropriate) | | | | |
| *P3a. Description (Describe resource and its major elements | . Include design, material | s, condition, alteratio | ns, size, se | etting, and bou | undaries) | |
| There are two separate structures on this parcel, although moderate pitched roof, also of corrugated metal material. C within fixed pane units, and are metal framed. Entry doors a S. Boyle Ave.) is a one-story, flat-roofed, rectangular brick s front entrance on the east facade, and two large symmetric building, is central to the south façade. Decorative brickwork in a square pattern. | One solid bank of windows are also metal, non-descri structure with minimal colo cally placed windows on e | is present on the from pt in nature. The seconial revival detailing. ither side of this prim | t of the struendary strue The structu ary entrywa | octure. Windon cture (listed on re has an arch ay. A parapet | ws are swing-type se the property as 5611 ed pediment over the 1/3 the length of the | |
| The setting is a mix of industrial and commercial. The build spurs. | | | by other li | ght industrial b | ouildings and railroad | |
| *P3b. Resource Attributes: (List attributes and codes) HP6 | | | | | | |
| *P4. Resources present: X Building Structure | Object Site | District Elem | ent of Dist | rict Oth | er (isolates, etc.) | |
| P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects) | | | | P5b. Description of Photo: (View, date, accession #) | | |
| | | | See C | ontinuation SI | neet for photos. | |
| See Continuation Sheet for photos. | | | Sourc | | cted/Age and X Historic Both | |
| | | | Farme Fred a Herbe 5511 s *P8. I affiliat Kelly I Parso 2233 s | and Mildred F ert Norman Tr S. Boyle Ave, Recorded by: ion, and addre Heidecker and | nant Trust Co. for fox Trust and fust Vernon, Ca. (Name, ess) Jeff Creighton e #330 | |
| | | | June : | Date Recorde 30, 2002 Survey Type: ive | | |
| *P11. Report Citation: (Cite survey report and other sources, | , or enter "none.") Malbui Report | rg Generating Statior t | Project C | ultural Resour | ces Inventory | |
| *Attachments: NONE X Location Map Sketch | n Map Conti | nuation Sheet | X Building | g, Structure, a | nd Object Record | |
| Archaeological Record District Record I | Linear Feature Record | Milling Station | Record | Rock A | art Record | |
| | Other (List): | <u> </u> | | | | |